
Airborne Instrumentation Research Project

Flight Summary Report

Flight No. 87-040

Date 10 December 1987



Science and Applications Aircraft Division



National Aeronautics and Space Administration

Ames Research Center Moffett Field, California 94035

FLIGHT SUMMARY REPORT

Flight Number: 87-040 Date: 10 December 1986

Julian Date: 344

Sensor Package: A-3 Configuration Aircraft No: 709

Purpose of Flight: 87x-001

Remarks:

Functional Check Flight

Area(s) Covered: San Luis Obispo/ Salinas Valley

SENSOR DATA

Accession No:	03612	03613	03614
Sensor ID No:	018	019	020
Sensor Type:	HR-732	HR-732	HR-732
Focal Length:	24" 609.6mm	24" 609.6mm	24" 609.6mm
Film Type:	High Definition Aerochrome Infrared, SO-131	Aerial Color, SO-242	Panatomic X Aerographic II, 2412
Filtration:	cc. 20B	None	Wratten-12
Spectral Band:	510-900nm	400-700nm	510-700nm
f Stop:	8	8	9.6
Shutter Speed:	1/75	1/75	1/75
No. of Frames:	30	39	39
% Overlap:	60	60	60
Quality:	Excellent	Excellent	Excellent

FLIGHT SUMMARY

87-040

This flight was a functional check of the A-3 configuration. Photographic coverage was accquired over San Luis Obispo, Santa Maria Valley and the upper Salinas Valley in California. No track map is provided for this flight.

All cameras operated noramlly and the areas flown were cloud-free. The SO-131 film ran out prior to the other two cameras due to a short film load. No malfunctions were noted and the quality of the data is rated excellent.

Sensor #	Check Points	Frame Numbers	Time (GMT-hr, min, sec)		Altitude War	Gland Garrers / Damaralan
			START	END	Altitude, MSL feet/meters	Cloud Cover/Remarks
018	V	0001-0004	19:59:57	20:00:26	65000/19800	clear-San Luis Obispo, CA
	3	0045-0049	20:19:32	20:20:31	11	clear-Santa Maria Valley, CA
		0050-0054	20:24:18	20:25:17	"	clear-clearing frames over N34 57/Wl20 13
		0055-0058	20:32:14	20:32:43	11	clear-San Luis Obispo, CA
		0059-0070	20:40:52	20:43:34	**	clear-Salinas Valley, CA
019/020		0001-0004	19:59:56	20:00:26	"	clear-San Luis Obispo, CA
	11	0045-0049	20:19:32	20:20:31	**	clear-Santa Maria Valley, CA
		0050-0054	20:24:18	20:25:17	"	clear-clearing frames over W34 57/W120 13
		0055-0058	20:32:14	20:32:43	99	clear-San Luis Obispo
vi.		0059-0079	20:40:52	20:45:47	11	clear-Salinas Valley
L						